

CAT Operator

Facility:	Written By:	Approved By:	Date Created:	Date of Last Revision

Hazards Present:	PPE or Devices Required:	Additional Training Required:
Other workers	Steel Toed Boots	Operator Training
Moving Equipment	Hard Hat	
Slip and Trip	Safety Glasses	
Pinch Points	High Vis Vest	

Safe Work Procedure:

- 1) Use cold start procedure and do pretrip inspection while machine is warming up
- 2) Check that:
 - there are no leaks or loose belts
 - lights and back up alarm are working
 - hydraulics are running properly
- 3) Mount and dismount machine using three point contact
- 4) Proceed to work area check steering and brakes as you go
- 5) Maintain proper distance from other workers and equipment and always look directly behind before backing up
- 6) Pay constant attention to all gauges
- 7) When stopped, check machine over and do not drag winch cable or have hook dangling loosely
- 8) Park in safe area and drop the hydraulics
- 9) Use hot shut down procedure
- 10) Check over machine and clean rad and tracks when finished

If an emergency situation occurs while conducting this task, or there is an equipment malfunction, engage the emergency stop and follow the lock out procedure

REPORT ANY HAZARDOUS SITUATIONS TO YOUR SUPERVISOR

<p>Guidance Documents/Standards:</p> <p>MB Workplace Safety & Health Act & Regulations:</p> <p>Part 6 Personal Protective Equipment Part 16 Machine, Tools and Robots Part 22 Powered Mobile Equipment</p>	<p>This Safe Work Procedure will be reviewed any time the task, equipment or materials change and at a minimum of every three years</p> <hr/> <p>Reviewed By WSH Committee:</p> <p>Date:</p>
---	---