

Load Skidsteer for Transport

Facility:	Written By:	Approved By:	Date Created:	Date of Last Revision

Hazards Present:	PPE or Devices Required:	Additional Training Required:
Slip/Trip hazard	Steel toed boots	Operator training
Fall injury	Safety glasses	
Vehicle/Machine damage	Hand protection	
Pinch points	Hard hat	

Safe Work Procedure:

- 1) Set ramp down on trailer.
- 2) Enter skidsteer using 3 point contact.
- 3) Drive up to ramp, make sure machine is properly aligned, and slowly drive on to trailer.
- 4) Engage brakes and ensure bobcat is in neutral.
- 5) Exit skidsteer using 3 point contact method. Dismount trailer with caution. Jumping off is prohibited.
- 6) Secure skidsteer with two chains using 4 point contact.
- 7) Load ramps.

If an emergency situation occurs while conducting this task, or there is an equipment malfunction, engage the emergency stop and follow the lock out procedure

REPORT ANY HAZARDOUS SITUATIONS TO YOUR SUPERVISOR

<p>Guidance Documents/Standards:</p> <p>MB Workplace Safety & Health Act & Regulations:</p> <p>4 General Workplace Requirements 6 Personal Protective Equipment 16 Machines, Tools and Robots 22 Powered Mobile Equipment</p>	<p>This Safe Work Procedure will be reviewed any time the task, equipment or materials change and at a minimum of every three years</p>
	<p>Reviewed By WSH Committee:</p> <p>Date:</p>