

Scaffold

<b>Facility:</b>	<b>Written By:</b>	<b>Approved By:</b>	<b>Date Created:</b>	<b>Date of Last Revision</b>

<b>Hazards Present:</b>	<b>PPE or Devices Required:</b>	<b>Additional Training Required:</b>
Fall injuries	Gloves	Scaffold training
Slip/Trip	Safety Glasses	Fall Training
Pinch points	Steel toed Boots	First Aid
Workers overhead/below	Hard Hat	
	Safety harness and tie off	

**Safe Work Procedure:**

- 1) Inspect all tubing and clamps thoroughly
- 2) Tape off or barricade any unsafe areas to warn others that there is overhead work
- 3) Ensure you are properly tied off at all times
- 4) Assemble scaffold according to manufacturer's instruction
- 5) When working high, raise and lower all tools etc. using a pull line. Ensure a proper bag is used for any clamps
- 6) Ensure work platform is clear from tripping hazards at all times
- 7) Immediately descend if any bad weather forms

***If an emergency situation occurs while conducting this task, or there is an equipment malfunction, engage the emergency stop and follow the lock out procedure***

**REPORT ANY HAZARDOUS SITUATIONS TO YOUR SUPERVISOR**

<b>Guidance Documents/Standards:</b> MB Workplace Safety & Health Act & Regulations: 5 First Aid 6 Personal Protective Equipment 28 Scaffolds and Other Elevated Work Platforms	This Safe Work Procedure will be reviewed any time the task, equipment or materials change and at a minimum of every three years
	Reviewed By WSH Committee:  Date: