

Catch Basin Installation

Facility:	Written By:	Approved By:	Date Created:	Date of Last Revision

Hazards Present:	PPE or Devices Required:	Additional Training Required:
Slips/trips	Hard Hat	Equipment operator certification
equipment malfunction	Steel Toed Boots	First Aid training
pinch points	Eye protection	
buried cables and services	Hand protection	
muscle strains		
overhead wires		

Safe Work Procedure:

- 1) Appoint a spotter who will be in charge of signaling the operator.
- 2) Assess and barricade the lift area (Job hazard analysis).
- 3) Position machine according to the center of gravity of the load.
- 4) Use approved slings/chains of the proper size and length.
- 5) Hook up of the load to be done by a competent rigger.
- 6) Lift when spotter signals safe to do so and the area is clear of personnel.
- 7) Move slowly to landing area and gently lower.
- 8) Ensure load is stable on level ground before securing slings/chains and unhooking.

If an emergency situation occurs while conducting this task, or there is an equipment malfunction, engage the emergency stop and follow the lock out procedure

REPORT ANY HAZARDOUS SITUATIONS TO YOUR SUPERVISOR

<p>Guidance Documents/Standards:</p> <p>MB Workplace Safety & Health Act & Regulations: 6 Personal Protection Equipment 4 First Aid 16 Machines, Tools and Robots 12 Hearing Conservation and Noise 23 Cranes and Hoists</p>	<p>This Safe Work Procedure will be reviewed any time the task, equipment or materials change and at a minimum of every three years</p>
	<p>Reviewed By WSH Committee:</p> <p>Date:</p>