

Powered Zip Cut

Facility:	Written By:	Approved By:	Date Created:	Date of Last Revision

Hazards Present:	PPE or Devices Required:	Additional Training Required:
Injury from cuts	Eye protection	
Noise levels	Hand protection	
Projectiles	Steel toe boots	
	Hearing protection	

Safe Work Procedure:

- 1) Use all required PPE
- 2) To be used for intended purposes
- 3) Cleaned and properly stored after use
- 4) Must have operational dead man control that requires constant hand pressure
- 5) All guards to be used and in good repair
- 6) Never hoist or lower by the power cord

If an emergency situation occurs while conducting this task, or there is an equipment malfunction, engage the emergency stop and follow the lock out procedure

REPORT ANY HAZARDOUS SITUATIONS TO YOUR SUPERVISOR

<p>Guidance Documents/Standards:</p> <p>MB Workplace Safety & Health Act & Regulations:</p> <p>2.1 Safe work procedure</p> <p>5 First Aid</p> <p>6 PPE</p>	<p>This Safe Work Procedure will be reviewed any time the task, equipment or materials change and at a minimum of every three years</p>
	<p>Reviewed By WSH Committee:</p> <p>Date:</p>