

Power Tools - General

Facility:	Written By:	Approved By:	Date Created:	Date of Last Revision

Hazards Present:	PPE or Devices Required:	Additional Training Required:
	Steel toed Boots	Manufacturer's Specifications
	Safety Glasses	
	Hard Hat	
	Hearing Protection	

Safe Work Procedure:
<ol style="list-style-type: none"> 1) Use all required PPE. 2) To be used for the intended purpose. 3) Cleaned and properly stored after usage. 4) Ensure that it has its own storage area to prevent damage. 5) Must have an operational dead man control that requires constant hand pressure. 6) Circular saws and chain saws must not be equipped with devices that lock onto the operating controls 7) All guards to be used and in good repair. 8) Never hoist or lower power tools by the power cord. 9) Ensure that tools is shut down while refueling.

If an emergency situation occurs while conducting this task, or there is an equipment malfunction, engage the emergency stop and follow the lock out procedure

REPORT ANY HAZARDOUS SITUATIONS TO YOUR SUPERVISOR

<p align="center">Guidance Documents/Standards:</p> <p align="center">MB Workplace Safety & Health Act & Regulations:</p> <p>4 General Workplace Requirements 5 First Aid 6 Personal Protective Equipment 16 Machines, Tools and Robots Division 1 16.22-16.28 Miscellaneous Machines & Tools</p>	<p>This Safe Work Procedure will be reviewed any time the task, equipment or materials change and at a minimum of every three years</p>
	<p>Reviewed By WSH Committee:</p> <p>Date:</p>